



Photo 1 – View of accident airplane windshield (courtesy of witness)



Photo 2 – Windshield from left side (courtesy of witness)



Photo 3 – Windshield from left side (courtesy of witness)



Photo 4 – Windshield as removed from fuselage (courtesy of witness)