



Photo 1 – View of Airplane on Gravel Overrun Pad (Courtesy of FAA)



Photo 2 – View of Airplane and Fuel Spill (Courtesy of FAA)



Photo 3 – View of Airplane Damage (Courtesy of FAA)



Photo 4 – View of Airplane Damage (Courtesy of FAA)



Photo 5 - View of Airplane Damage (Courtesy of FAA)



Photo 6 – View of Landing Gear Impact (Courtesy of FAA)



Photo 7 – View of Localizer Antenna and Freeway Proximity (Courtesy of FAA)



Photo 8 – View of Flaps at SF2 (Courtesy of FAA)



Photo 9 – View of Stabilizer Trim Setting (Courtesy of FAA)



Photo 10 – View of Stabilizer Trim Setting (Courtesy of FAA)