



**Photo 1 – Accident site, view from the approaching helicopter.(Courtesy of Air Transport)**



**Photo 2 - Accident site, view of the main wreckage.(Courtesy of Air Transport)**



**Photo 3 - Accident site, view of the debris field.(Courtesy of Air Transport)**



**Photo 4 - Accident site, view of the main wreckage.(Courtesy of Air Transport)**



**Photo 5 - Accident site, view of the debris field and rudder. (Courtesy of Air Transport)**



**Photo 6 - Accident site, view of the main wreckage.(Courtesy of Air Transport)**