



Photo 1 – Front view of fuselage damage (photo courtesy of first responders)



Photo 2 - View of right side fuselage & wing damage (photo courtesy of first responders)



Photo 3 - View of left side fuselage & wing damage (photo courtesy of first responders)



Photo 4 - View of pilot rated student right leg in similar airplane while seated normally (photo courtesy of the operator)



Photo 5 - View of pilot rated student right leg in similar airplane while simulating negative G (photo courtesy of the operator)




Photo 6 - View of pilot's left boot (photo courtesy of the operator)



Photo 7 - View of pilot's left leg G-suit damage (photo courtesy of the pilot)