

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Chandler Municipal Airport (KCHD) State: AZ

ZIP: 85286 Country: United States

Latitude: 33.27°N Longitude: 111.81°W

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 07/10/2021 Local Time: 0730

mm/dd/yyyy

Time Zone: MST

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N222HC

Manufacturer: Beechcraft

Model: A36TC

Serial Number: EA-259

Year of Manufacture: 1981

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

☒ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 3849 lbs

Weight at Time of Accident/Incident: 3794 lbs

Number of Seats: 6 Flight Crew Seats: 1

Cabin Crew Seats: 0 Passenger Seats: 3

Number of Engines: One

Category of Aircraft

- ☒ Airplane
- ☐ Balloon
- ☐ Blimp/Dirigible
- ☐ Glider
- ☐ Gyroplane
- ☐ Helicopter
- ☐ Powered Lift
- ☐ Rocket
- ☐ Ultralight
- ☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
- ☐ Aerobatic
- ☐ Balloon
- ☐ Commuter
- ☐ Transport
- ☐ Utility

Special

- ☐ Restricted
- ☐ Limited
- ☐ Provisional
- ☐ Special Flight
- ☐ Experimental
- ☐ Special Light-Sport
- ☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)

☐ None

☐ Unknown

Landing Gear

(Check all that apply)

☒ Retractable

- ☒ Tricycle
- ☐ Amphibian
- ☐ Emergency Float
- ☐ Float
- ☐ Hull
- ☐ Tailwheel
- ☐ High Skid
- ☐ Skid
- ☐ Ski
- ☐ Ski/Wheel
- ☐ Other Launch/Recovery System
- ☐ None
- ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating
- ☐ Turbo Shaft
- ☐ Turbo Prop
- ☐ Turbo Jet
- ☐ Turbo Fan
- ☐ Electric
- ☐ Liquid Rocket
- ☐ Solid Rocket
- ☐ Hybrid Rocket
- ☐ None
- ☐ Unknown

Fuel System Type (Reciprocating)

- ☐ Carburetor
- ☒ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	TCM	TSIO-520-UB6B	248980-R	02/05/1992	300	2261		899
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour
- ☐ AAIP
- ☒ Annual
- ☐ Continuous Airworthiness
- ☐ Conditional Inspection
- ☐ Unknown

Date Last Inspection: 06/13/2021
mm/dd/yyyy

Airframe Total Time: 4491 hrs

hours measured at (Select one)

- ☐ Last Inspection
- ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
- ☐ Conditional (Amateur-built only)
- ☐ Manufacturer's Inspection Program
- ☐ Other Approved Inspection Program (AAIP)
- ☐ Continuous Airworthiness
- ☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
- ☐ Specify: _____

Propeller 1

- ☐ Fixed Pitch
- ☒ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: Hartzell

Model: PHC-C3YF-1RF/F8068K

Propeller 2

- ☐ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: ACR

Model or Part No.: ME406

TSO No.: ☐ OC91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☒ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☒ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☒ No

If not activated:

- Indicate Reason:
- ☐ Impact Damage
 - ☐ Fire Damage
 - ☐ Battery Expired/Damaged
 - ☐ Unknown

Additional Equipment (Check all that apply)

- ☒ ADS-B
- ☐ Airframe Parachute
- ☐ Angle of Attack Indicator
- ☒ Autopilot
- ☐ Data Recorder
- ☒ Electronic Flight Bag or Handheld Device
- ☒ Electronic Multifunction Display
- ☒ Electronic Primary Flight Display
- ☐ Handheld GPS
- ☐ Heads Up Display
- ☒ Onboard Weather
- ☐ Satellite Tracking Device
- ☒ Stall Warning System
- ☐ Video Recording Device
- ☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Mudd Flyers LLCCity: ManassasFractional Ownership Aircraft: ☐ Yes ☒ NoState: VA ZIP: 22192Country: USA**Operator of Aircraft**☐ Same As Registered Owner☒ Same Address as Registered OwnerName: Marty Mosier

City: _____

Doing Business As: _____

State: _____ ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: Chandler Municipal AirportDistance From Airport Center: 0.5 smAirport Identifier: KCHDDirection From Airport: on airport degrees trueProximity to Airport: ☐ Off Airport/Airstrip ☒ On Airport/Airstrip ☐ N/AAirport Elevation: 1243 ft. msl**Runway Information**Runway ID: 22R (L/R/C) Length: 4401 ft Width: 75 ft**Runway/Landing Surface (Check all that apply)**

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☒ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☒ None
- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Marty City of Residence: Woodbridge
 Middle Initial: R State: VA ZIP: 22192
 Last Name: Mosier Country: USA
 Age at time of Accident/Incident: 65 Date of Birth: 06/26/2021 mm/dd/yyyy
 Certificate Number: [REDACTED]

Degree of Injury ☐ None ☐ Fatal ☐ Minor ☒ Unknown ☐ Serious	Seat Occupied ☐ Left ☐ Front ☐ Unknown ☒ Right ☐ Rear ☐ Center ☐ Single	Restraint Type <table style="width: 100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap only</td> <td>☐ Lap only</td> </tr> <tr> <td>☐ 3-point</td> <td>☐ 3-point</td> </tr> <tr> <td>☒ 4-point</td> <td>☒ 4-point</td> </tr> <tr> <td>☐ 5-point</td> <td>☐ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table>	Available	Used	☐ None	☐ None	☐ Lap only	☐ Lap only	☐ 3-point	☐ 3-point	☒ 4-point	☒ 4-point	☐ 5-point	☐ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Available	Used																
☐ None	☐ None																
☐ Lap only	☐ Lap only																
☐ 3-point	☐ 3-point																
☒ 4-point	☒ 4-point																
☐ 5-point	☐ 5-point																
☐ Unknown	☐ Unknown																
Pilot Certificate(s) (Check all that apply) ☐ None ☒ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☒ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer																	

Principal Occupation ☐ Pilot ☒ Other ☐ Unknown	Medical Certificate ☐ None ☒ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown	Medical Certificate Validity ☐ Without limitations/waivers ☐ Unknown ☒ With limitations/waivers ☐ N/A ☐ Special Issuance	Date of Last Medical <u>01/07/2021</u> mm/dd/yyyy
---	---	---	--

Medical Certificate Limitations

Corrective Glasses

Medical Certificate Special Issuance

Special Issuance; Not valid after January 2022

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: <u>06/26/2021</u> mm/dd/yyyy	Flight Review Aircraft Make: <u>Beechcraft</u> Model: <u>A36TC</u>
---	---

Airplane Rating(s) (Check all that apply) ☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☒ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) (Check all that apply) ☒ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) (Check all that apply) ☐ None ☒ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) (Check all that apply) ☐ None ☒ Instrument Airplane ☒ Airplane Single-Engine ☐ Instrument Helicopter ☒ Airplane Multi-Engine ☐ Helicopter ☐ Gyroplane ☐ Glider ☐ Powered Lift ☐ Sport
--	--	--	--

Type Ratings	Student Endorsements (Include dates)
---------------------	---

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	2,026	1,293	1,701	325	223	286	84	0	0	0
Pilot in Command (PIC)	1,913	1,293	1,588	300	223	286	50	0	0	0
Time as Instructor	100	100	100	0	10	5	10	0	0	0
This Make/Model					180	230	20			
Last 90 Days	54	54	54	0	0	7	0	0	0	0
Last 30 Days	22	22	22	0	0	3	0	0	0	0
Last 24 Hours	0	0	0	0	0	0	0	0	0	0

"FLIGHT CREWMEMBER 2" INFORMATION**"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident**

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: _____

City of Residence: _____

Middle Initial: _____

State: _____ ZIP: _____

Last Name: _____

Country: _____

Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy

Certificate Number: _____

Degree of Injury

☐ None
 ☐ Fatal
☐ Minor
 ☐ Unknown
☐ Serious

Seat Occupied

☐ Left
 ☐ Front
 ☐ Unknown
☐ Right
 ☐ Rear
☐ Center
 ☐ Single

Restraint Type**Available**

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None
 ☐ Flight Instructor
 ☐ Commercial
 ☐ US Military
☐ Private
 ☐ Recreational
 ☐ Airline Transport
 ☐ Foreign
☐ Student
 ☐ Sport
 ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None
 ☐ Class 3
☐ Class 1
 ☐ Driver's License (Sport Pilot only)
☐ Class 2
 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers
 ☐ Unknown
☐ With limitations/waivers
 ☐ N/A
☐ Special Issuance

Date of Last Medical

_____ mm/dd/yyyy

Medical Certificate Limitations**Medical Certificate Special Issuance****Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:**

_____ mm/dd/yyyy

Flight Review Aircraft

Make: _____

Model: _____

Airplane Rating(s)
(Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)
(Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)
(Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)
(Check all that apply)

☐ None
 ☐ Instrument Airplane
☐ Airplane Single-Engine
 ☐ Instrument Helicopter
☐ Airplane Multi-Engine
 ☐ Helicopter
☐ Gyroplane
 ☐ Glider
☐ Powered Lift
 ☐ Sport

Type Ratings**Student Endorsements** (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer					Restraint Type: Available Used ☐ None ☐ None ☐ Lap Only ☐ Lap Only ☐ 3-point ☐ 3-point ☐ 4-point ☐ 4-point ☐ 5-point ☐ 5-point ☐ Unknown ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer					Restraint Type: Available Used ☐ None ☐ None ☐ Lap Only ☐ Lap Only ☐ 3-point ☐ 3-point ☐ 4-point ☐ 4-point ☐ 5-point ☐ 5-point ☐ Unknown ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: <u>Jennifer</u> City : <u>Woodbridge</u> Middle Initial: <u>R</u> State: <u>VA</u> ZIP: <u>22192</u> Last Name: <u>Sterling</u> Country: <u>USA</u> ☐ Crew ☒ Passenger ☐ Other			☒ Left ☐ Center ☐ Right ☐ Unknown Row: <u>2</u>	☐ None ☐ Minor ☐ Serious ☐ Fatal ☒ Unknown	Available ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: <u>Donald</u> City : <u>Mesa</u> Middle Initial: <u>W</u> State: <u>AZ</u> ZIP: <u>85202</u> Last Name: <u>Hiatt</u> Country: <u>USA</u> ☐ Crew ☒ Passenger ☐ Other			☒ Left ☐ Center ☐ Right ☐ Unknown Row: <u>1</u>	☐ None ☐ Minor ☐ Serious ☐ Fatal ☒ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☒ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☒ 4-point ☐ 5-point ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: <u>Barbara</u> City : <u>Mesa</u> Middle Initial: _____ State: <u>AZ</u> ZIP: <u>85202</u> Last Name: <u>Hiatt</u> Country: <u>USA</u> ☐ Crew ☒ Passenger ☐ Other			☐ Left ☐ Center ☒ Right ☐ Unknown Row: <u>2</u>	☐ None ☐ Minor ☐ Serious ☐ Fatal ☒ Unknown	Available ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>KCHD</u> City: <u>Chandler</u> State: <u>AZ</u> Country: <u>USA</u>	Time of Departure Time: <u>0730</u> Time Zone: <u>MST</u>	Destination Airport ID: <u>KSEZ</u> City: <u>Sedona</u> State: <u>AZ</u> Country: <u>USA</u>	Type Flight Plan Filed ☒ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☐ Yes ☒ No ☐ Unknown
--	--	---	--

Type of ATC Clearance/Service (Check all that apply)				
☐ None	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☒ VFR	☐ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)				Altitude of In-Flight Occurrence: <u>1273</u> ft msl
☐ Class A	☐ Class G	☐ Military Operations Area (MOA)	☐ Special	
☐ Class B	☐ Demo Area	☐ Airport Advisory Area	☐ Air Traffic Control Area	
☐ Class C	☐ Warning Area	☐ Jet Training Area	☐ Unknown	
☒ Class D	☐ Prohibited Area	☐ TRSA		
☐ Class E	☐ Restricted Area	☐ FAR 93		

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information (Check all that apply)	Weather Observation Facility
☐ National Weather Service ☐ Flight Service Station ☐ TV/Radio ☐ Automated Report ☒ Commercial Weather Service (DUATS) ☒ On-Board Weather	Facility ID: <u>KCHD</u> Observation Time: <u>Unknown</u> Time Zone: <u>MST</u> Distance from Accident Site: <u>0</u> nm Direction from Accident Site: _____ degrees true
☐ Company ☐ Military ☒ Internet ☐ None ☐ Unknown	

Basic Conditions ☒ VMC ☐ IMC ☐ Unknown	Light Condition ☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown ☒ Day ☐ Night ☐ Bright Night
---	---

Sky/Lowest Cloud Condition ☒ Clear ☐ Thin Broken ☐ Few ☐ Thin Overcast ☐ Partial Obscuration ☐ Unknown ☐ Scattered	Ceiling ☒ None (Clear) ☐ Obscured ☐ Broken ☐ Indefinite ☐ Overcast ☐ Unknown	Temperature: _____ (C) or <u>90</u> (F) Dew Point: _____ (C) or <u>Unk</u> (F) Altimeter Setting: <u>Unk</u> in. Hg or _____ MB
Lowest Cloud Condition Height _____ ft agl	Ceiling Height _____ ft agl	

Wind Direction ☐ Variable -or- Direction: <u>Unk</u> degrees true	Wind Speed ☐ Calm ☐ Light and Variable -or- Speed: <u>Unk</u> kts	Wind Gusts ☒ Not Gusting -or- Speed: _____ kts	Visibility <u>> 10</u> miles RVR: _____ feet RVV: _____ miles Density Altitude: <u>3600</u> ft
--	--	--	--

Intensity of Precipitation ☐ Light ☐ Moderate ☐ Heavy ☒ N/A ☐ Unknown	Type of Precipitation (Check all that apply)	Restriction to Visibility (Check all that apply)
	☒ None ☐ Drizzle ☐ Freezing Rain ☐ Rain ☐ Ice Pellets ☐ Snow Shower ☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower ☐ Hail ☐ Snow Grains ☐ Freezing Drizzle ☐ Rain Showers ☐ Ice Crystals	☒ None ☐ Fog ☐ Blowing Dust ☐ Ground Fog ☐ Blowing Sand ☐ Haze ☐ Blowing Snow ☐ Ice Fog ☐ Blowing Spray ☐ Smoke ☐ Dust ☐ Unknown

Icing Forecast	Icing Actual	Turbulence																																						
<table border="0"> <tr> <th>Amount</th> <th>Type</th> </tr> <tr> <td>☒ None</td> <td>☐ N/A</td> </tr> <tr> <td>☐ Trace</td> <td>☐ Rime</td> </tr> <tr> <td>☐ Light</td> <td>☐ Clear</td> </tr> <tr> <td>☐ Moderate</td> <td>☐ Mixed</td> </tr> <tr> <td>☐ Severe</td> <td>☐ Unknown</td> </tr> <tr> <td>☐ Unknown</td> <td></td> </tr> </table>	Amount	Type	☒ None	☐ N/A	☐ Trace	☐ Rime	☐ Light	☐ Clear	☐ Moderate	☐ Mixed	☐ Severe	☐ Unknown	☐ Unknown		<table border="0"> <tr> <th>Amount</th> <th>Type</th> </tr> <tr> <td>☒ None</td> <td>☐ N/A</td> </tr> <tr> <td>☐ Trace</td> <td>☐ Rime</td> </tr> <tr> <td>☐ Light</td> <td>☐ Clear</td> </tr> <tr> <td>☐ Moderate</td> <td>☐ Mixed</td> </tr> <tr> <td>☐ Severe</td> <td>☐ Unknown</td> </tr> <tr> <td>☐ Unknown</td> <td></td> </tr> </table>	Amount	Type	☒ None	☐ N/A	☐ Trace	☐ Rime	☐ Light	☐ Clear	☐ Moderate	☐ Mixed	☐ Severe	☐ Unknown	☐ Unknown		<table border="0"> <tr> <th>Type (Check all that apply)</th> <th>Severity</th> </tr> <tr> <td>☒ None</td> <td>☐ Light</td> </tr> <tr> <td>☐ Clear Air</td> <td>☐ Moderate</td> </tr> <tr> <td>☐ Terrain-Induced</td> <td>☐ Severe</td> </tr> <tr> <td>☐ Convective Turbulence</td> <td>☐ Extreme</td> </tr> </table>	Type (Check all that apply)	Severity	☒ None	☐ Light	☐ Clear Air	☐ Moderate	☐ Terrain-Induced	☐ Severe	☐ Convective Turbulence	☐ Extreme
Amount	Type																																							
☒ None	☐ N/A																																							
☐ Trace	☐ Rime																																							
☐ Light	☐ Clear																																							
☐ Moderate	☐ Mixed																																							
☐ Severe	☐ Unknown																																							
☐ Unknown																																								
Amount	Type																																							
☒ None	☐ N/A																																							
☐ Trace	☐ Rime																																							
☐ Light	☐ Clear																																							
☐ Moderate	☐ Mixed																																							
☐ Severe	☐ Unknown																																							
☐ Unknown																																								
Type (Check all that apply)	Severity																																							
☒ None	☐ Light																																							
☐ Clear Air	☐ Moderate																																							
☐ Terrain-Induced	☐ Severe																																							
☐ Convective Turbulence	☐ Extreme																																							

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

None that I can recall as being pertinent.

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☐ Substantial
☐ Minor ☒ Destroyed
 ☐ Unknown

Aircraft Fire

- ☐ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☒ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Aircraft totally destroyed by post impact fire. Impacted airport perimeter chain link fence which was locally damaged where aircraft made contact with fence and posts.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

Plane is based in Manassas, VA and had been flown to Chandler for family visits. I have been flying to Chandler almost every year for the last 14 years. I am familiar with the airport and high OAT operations. I have taken off and landed on both runways at CHD in a variety of weight and balance configurations up to full gross weight and higher OAT.

This was a VFR pleasure flight from Chandler Municipal Airport (KCHD) to Sedona Airport (KSEZ). I was flying as PIC from the right seat with a passenger in the left seat. Two passengers were in the second row seats which were facing forward. I was not providing flight instruction. No baggage other than travel kit with several quarts of oil and small ice chest with six bottles of water.

The airplane has fully functional dual control wheels with the Bonanza exposed cross bar configuration. Instrumentation included a full glass cockpit with Garmin GTN 750 and 650, G500, 930 engine management display and S-tec 55 autopilot.

Weight and balance analysis calculated prior to the flight with planned take off fuel load was approximately 50 lbs. below MGTOW and well within GC envelope. CG changes with fuel burn were such that the aircraft would remain within CG envelope throughout the flight. Takeoff distance calculation using AFM graphs assuming 90-degree OAT was approximately 3,000 feet over 50 foot obstacle. Runway length (22R) is 4,401 feet.

Preflight inspection was conducted normally. Fuel load was verified to at or about the tabs (54 gallons useable total in the two main wing tanks). Tip tanks were full (20 gallons each). Only anomaly observed was that the pitot cover was missing, having apparently blown off during the windstorm that occurred at KCHD the preceding night. No water was observed in any of the fuel sumps.

Engine start, taxi and pre-takeoff were normal. Left and right magneto checks showed approximately 50 RPM drop within allowances. Cylinder head and EGT indications on 930 engine analyzer appeared typical. Oil temperature and other parameters were within limits for takeoff.

When cleared for takeoff the aircraft was positioned near the end of Runway 22R, brakes applied and the engine advanced to full power. Engine sound and indications appeared nominal. Turbocharger appeared to engage normally at approximately 25 inches MP.

When full power was reached, the brakes were released, and the aircraft began accelerating. Acceleration was observed to be slightly slower than expected and the ground roll somewhat longer than predicted but given the high OAT this was not interpreted as being indicative of a problem.

Rotation was normal. Once the aircraft cleared the ground the nose was lowered to allow the plane to accelerate. Normal takeoff procedure after rotation is to allow the plane to accelerate to 120 knots while initially climbing for proper engine cooling. The TSIO 520UB engine can easily overheat at high OAT at low airspeed.

Once a positive ROC was observed the gear was raised. Retraction was normal.

The aircraft was not able to accelerate and climb. Although the plane was felt to be somewhat out trim it was readily correctable. Holding altitude resulted in the airspeed deteriorating rather than increasing as expected. My focus was on maintaining airspeed and attempting to climb so I am not sure what was on the engine monitor, but the plane was not behaving the way it normally does at that point in flight. The plane behaved as if the engine was not generating sufficient power to maintain flight.

The situation was determined to be untenable with further attempt at flight deemed inadvisable. At this point the aircraft was still over but near the end of the runway but the altitude was below obstacles outside the airport perimeter, and we did not appear able to climb.

I made the decision to put the plane on the ground in a controlled manner rather than attempt to continue flight given the obstacles surrounding the airport.

The nose was lowered and flown to a flare just beyond the departure end of Runway 22R. There is a few hundred feet of dirt with minimal desert vegetation as an overrun area beyond the Runway 22R.

The aircraft impacted wings level gear up. The aircraft slid along the dirt and came to rest against the airport fence to the right of the extended centerline of Runway 22R. All passengers were properly restrained with the pilot and co-pilot positions having four-point harnesses.

Unfortunately, the ground skid and subsequent impact with the fence apparently damaged the left leading edge just outboard of the fuselage. This is the location of the left wing main fuel tank. A fire started on the left side of the engine compartment. Very noticeable impact damage can be seen to the plane left leading edge near the fuselage which is the location of the left main fuel tank.

I immediately exited the aircraft using the front access door and opened the rear cargo access doors. The rear seat passengers exited the plane out the rear cargo door. The other passengers exited the plane out the front access door. Everyone gathered aft of the plane

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☒ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

The engine did not appear to be generating sufficient power to continue flight, although it developed sufficient power for a normal takeoff roll, rotation, and entry into ground effect.

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

94 Gallons**Fuel Type**☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive**Other Services, if Any, Prior to Departure****EVACUATION OF AIRCRAFT**Was an emergency evacuation of the aircraft performed? ☒ Yes ☐ No**Method of Exit** – Describe how the occupants exited and how many occupants evacuated each location

Pilot and front row passenger exited through the forward right side passenger access door. The two second row passengers exited through the cargo/passenger access door located on the right side of the fuselage aft of the wing.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)**Aircraft Registration Number**

Manufacturer: _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

08/4/2021

mm/dd/yyyy

Name of Pilot/Operator: Marty R. Mosier

Signature: _____

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

WPR21LA287

Reviewed by NTSB Regional Office

WPR

Name of Investigator

James M. Bledsoe

Date Report Received

8/9/2021