



Photo 1 – Accident site, initial tree strike.
(Courtesy of the Santa Cruz County Sheriff's Office)



Photo 2 – Accident site, main wreckage.
(Courtesy of the Santa Cruz County Sheriff's Office)



**Photo 3 – Accident site, view of the propeller assembly and engine cowling.
(Courtesy of the Santa Cruz County Sheriff's Office)**



**Photo 4 – Accident site, view from near the initial tree strike.
(Courtesy of the Santa Cruz County Sheriff's Office)**