

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Chandler Municipal Airport State: AZ

ZIP: 85297 Country: USA

Latitude: 33.2630 Longitude: -111.8180

(Enter in decimal degrees or degrees minutes seconds)

Accident/Incident Date/Time

Date: 10/01/2021 Local Time: 7:40am
mm/dd/yyyy

Time Zone: MST

Collision with Other Aircraft: ☒ Midair ☐ On-ground ☐ None

AIRCRAFT INFORMATION

Registration Number: N2868H

Manufacturer: Piper

Model: PA-28-181

Serial Number: 28-7990508

Year of Manufacture: 1979

Amateur-Built: ☐ Yes ☒ No If Yes ☐ Kit/Plans ☐ Original Design Make: _____

☒ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 2550 lbs

Weight at Time of Accident/Incident: 2073.3 lbs

Number of Seats: 4 Flight Crew Seats: 2

Cabin Crew Seats: 0 Passenger Seats: 2

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
- ☐ Balloon
- ☐ Blimp/Dirigible
- ☐ Glider
- ☐ Gyroplane
- ☐ Helicopter
- ☐ Powered Lift
- ☐ Rocket
- ☐ Ultralight
- ☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
- ☐ Restricted
- ☐ Aerobatic
- ☐ Limited
- ☐ Balloon
- ☐ Provisional
- ☐ Commuter
- ☐ Special Flight
- ☐ Transport
- ☐ Experimental
- ☐ Utility
- ☐ Special Light-Sport
- ☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)

☐ None

☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☒ Tricycle
- ☐ Tailwheel
- ☐ Amphibian
- ☐ High Skid
- ☐ Emergency Float
- ☐ Skid
- ☐ Float
- ☐ Ski
- ☐ Hull
- ☐ Ski/Wheel
- ☐ Other Launch/Recovery System
- ☐ None
- ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating
- ☐ Liquid Rocket
- ☐ Turbo Shaft
- ☐ Solid Rocket
- ☐ Turbo Prop
- ☐ Hybrid Rocket
- ☐ Turbo Jet
- ☐ None
- ☐ Turbo Fan
- ☐ Unknown
- ☐ Electric

Fuel System Type (Reciprocating)

- ☒ Carburetor
- ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☐ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng 1								
Eng 2								
Eng 3								
Eng 4								

Last Inspection Type

- ☐ 100-Hour
- ☐ Continuous Airworthiness
- ☐ AAIP
- ☐ Conditional Inspection
- ☐ Annual
- ☐ Unknown

Date Last Inspection: _____
mm/dd/yyyy

Airframe Total Time: _____ hrs

hours measured at (Select one)

- ☐ Last Inspection
- ☐ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
- ☐ Conditional (Amateur-built only)
- ☐ Manufacturer's Inspection Program
- ☐ Other Approved Inspection Program (AAIP)
- ☐ Continuous Airworthiness
- ☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
- ☐ Specify: _____

Propeller 1

- ☒ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: _____

Model: _____

Propeller 2

- ☐ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes

ELT Manufacturer: _____

Model or Part No.: _____

TSO No.: ☐ OC91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☐ OC126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☒ No

If activated

Did ELT Aid in Locating Aircraft? ☐ Yes ☐ No

If not activated

- Indicate Reason:
- ☐ Impact Damage
 - ☐ Fire Damage
 - ☐ Battery Expired/Damaged
 - ☒ Unknown

Additional Equipment (Check all that apply)

- ☒ ADS-B
- ☐ Airframe Parachute
- ☐ Angle of Attack Indicator
- ☐ Autopilot
- ☐ Data Recorder
- ☒ Electronic Flight Bag or Handheld Device
- ☐ Electronic Multifunction Display
- ☐ Electronic Primary Flight Display
- ☒ Handheld GPS
- ☐ Heads Up Display
- ☒ Onboard Weather
- ☐ Satellite Tracking Device
- ☒ Stall Warning System
- ☐ Video Recording Device
- ☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: FLIGHT OPERATIONS ACADEMY LLCCity: ChandlerState: AZZIP: 85297Fractional Ownership Aircraft: ☐ Yes ☒ NoCountry: USA**Operator of Aircraft**☐ Same As Registered Owner☐ Same Address as Registered OwnerName: William Summerfield DubelCity: GilbertDoing Business As: Flight InstructorState: AZZIP: 85297

Air Carrier/Operator Designator (4 Character Code): _____

Country: USA**Operating Certificates Held**

(Check all that apply)

- ☐ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☒ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☐ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)Airport Name: Chandler Municipal AirportDistance From Airport Center: 0.6 smAirport Identifier: KCHDDirection From Airport: 220 degrees trueProximity to Airport: ☐ Off Airport/Airstrip ☒ On Airport/Airstrip ☐ N/AAirport Elevation: 1243 ft. msl**Runway Information**Runway ID: 04R (L/R/C) Length: 4870 ft Width: 75 ft**Runway/Landing Surface** (Check all that apply)

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☒ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☒ Touch and Go
☐ Valley/Terrain Following ☒ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

“Flight Crewmember 1” Responsibilities at the Time of Accident/Incident

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

First Name: William

City of Residence: Gilbert

Middle Initial: S

State: AZ ZIP: 85297

Last Name: Dubel

Country: USA

Age at time of Accident/Incident: 43 Date of Birth: [REDACTED] mm/dd/yyyy

Certificate Number: [REDACTED]

Principal Occupation	Medical Certificate	Medical Certificate Validity	Date of Last Medical
☒ Pilot ☐ Other ☐ Unknown	☐ None ☐ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☒ Class 2 ☐ Unknown	☐ Without limitations/waivers ☐ Unknown ☒ With limitations/waivers ☐ N/A ☐ Special Issuance	<u>01/04/2021</u> <i>mm/dd/yyyy</i>

Must have available glasses for near vision.

**Date of Last Flight Review
or Equivalent, Including**

08/23/2021
mm/dd/yyyy

Make: Piper

Model: PA-28-181

Type Ratings	Student Endorsements <i>(Include dates)</i>

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	425	115	413	12	49	0	70	0	0	0
Pilot in Command (PIC)	344	115	342	2	46	0	70	0	0	0
Time as Instructor	32	14	32	0	2	0	0	0	0	0
This Make/Model					4	0	49			
Last 90 Days	46	29	46	0	0	0	6	0	0	0
Last 30 Days	14	8	14	0	0	0	1	0	0	0
Last 24 Hours	3	1	3	0	0	0	0	0	0	0

☐ Pilot ☐ Co-Pilot ☒ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

City of Residence: **Phoenix**

State: **Arizona** ZIP: **85048**

Country:

Certificate Number: [REDACTED]

Degree of Injury ☒ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious		Seat Occupied ☒ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single		Restraint Type Available ☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Pilot Certificate(s) <i>(Check all that apply)</i> ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☒ Student ☐ Sport ☐ Flight Engineer						
Principal Occupation ☐ Pilot ☐ Other ☐ Unknown	Medical Certificate ☐ None ☒ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown		Medical Certificate Validity ☒ Without limitations/waivers ☐ Unknown ☐ With limitations/waivers ☐ N/A ☐ Special Issuance		Date of Last Medical <u>07/19/2021</u> <i>mm/dd/yyyy</i>	

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: _____ <i>mm/dd/yyyy</i>	Flight Review Aircraft Make: _____ Model: _____
---	--

Airplane Rating(s) <i>(Check all that apply)</i> ☒ None ☐ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) <i>(Check all that apply)</i> ☒ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) <i>(Check all that apply)</i> ☒ None ☐ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) <i>(Check all that apply)</i> ☒ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport
--	---	---	--

Type Ratings	Student Endorsements <i>(Include dates)</i>

Flight Time <i>(Enter appropriate number of hours in each box)</i>	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	15	15	15	0	0	0	0	0	0	0
Pilot in Command (PIC)	0	0	0	0	0	0	0	0	0	0
Time as Instructor	0	0	0	0	0	0	0	0	0	0
This Make/Model					0	0	0			
Last 90 Days	14	0	0	0	0	0	0	0	0	0
Last 30 Days	8	0	0	0	0	0	0	0	0	0
Last 24 Hours	1	0	0	0	0	0	0	0	0	0

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>KCHD</u> City: <u>Chandler</u> State: <u>AZ</u> Country: <u>USA</u>	Time of Departure Time: <u>06:30am</u> Time Zone: <u>MST</u>	Destination Airport ID: <u>KCHD</u> City: <u>Chandler</u> State: <u>AZ</u> Country: <u>USA</u>	Type Flight Plan Filed ☒ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☐ Yes ☒ No ☐ Unknown
--	---	---	--

Type of ATC Clearance/Service (Check all that apply)

☐ None	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☒ VFR	☐ IFR	☐ VFR On Top	☒ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☐ Class B ☐ Class C ☒ Class D ☐ Class E	☐ Class G ☐ Demo Area ☐ Warning Area ☐ Prohibited Area ☐ Restricted Area	☐ Military Operations Area (MOA) ☐ Airport Advisory Area ☐ Jet Training Area ☐ TRSA ☐ FAR 93	☐ Special ☐ Air Traffic Control Area ☐ Unknown	Altitude of In-Flight Occurrence: <u>1500</u> ft msl
---	---	---	---	--

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☐ National Weather Service ☐ Flight Service Station ☐ TV/Radio ☒ Automated Report ☐ Commercial Weather Service (DUATS) ☒ On-Board Weather	☐ Company ☐ Military ☒ Internet ☐ None ☐ Unknown
--	--

Weather Observation Facility

Facility ID: KCHD
 Observation Time: 1247
 Time Zone: GMT
 Distance from Accident Site: 1 nm
 Direction from Accident Site: 210 degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☒ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Lowest Cloud Condition Height

_____ ft agl

Ceiling

☒ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Ceiling Height

_____ ft agl

Temperature: 20 (C) or _____ (F)

Dew Point: 9 (C) or _____ (F)

Altimeter Setting: 29.99 in. Hg
 or _____ MB

Wind Direction

☐ Variable

-or-
Direction: 040 degrees true

Wind Speed

☐ Calm
☐ Light and Variable

-or-
Speed: 6 kts

Wind Gusts

☒ Not Gusting

-or-
Speed: _____ kts

Visibility 30 miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: 2100 ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☒ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None	☐ Drizzle	☐ Freezing Rain
☐ Rain	☐ Ice Pellets	☐ Snow Shower
☐ Snow	☐ Snow Pellets	☐ Ice Pellets Shower
☐ Hail	☐ Snow Grains	☐ Freezing Drizzle
☐ Rain Showers	☐ Ice Crystals	

Restriction to Visibility (Check all that apply)

☒ None	☐ Fog
☐ Blowing Dust	☐ Ground Fog
☐ Blowing Sand	☐ Haze
☐ Blowing Snow	☐ Ice Fog
☐ Blowing Spray	☐ Smoke
☐ Dust	☐ Unknown

Icing Forecast

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Icing Actual

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Turbulence

Type (Check all that apply)	Severity
☒ None	☐ Light
☐ Clear Air	☐ Moderate
☐ Terrain-Induced	☐ Severe
☐ Convective Turbulence	☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

Taxiway charlie closed

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property (Use additional sheet if necessary)

Left main landing gear sheered off. Left brake line free. Right gear strut shroud damaged. Nose wheel broken off. Both propeller tips bent. Minor sheet metal denting on left flap.

NARRATIVE HISTORY OF FLIGHT (Please type or print in ink)

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

On the evening of September 30, 2021, Jason Houle (student) and I (instructor) briefed the training intent. We planned to stay in the pattern and practice landings. The following morning, I met with my student at the ramp at 6:00am local time. Jason had called for fuel and in the meanwhile I reviewed his preflight and the instructional plan of the day - landings with focus on the roundout and touchdown. We started the engine around 6:25am. Jason requested "touch and go's with Sierra". We taxied to runup at 4L behind an aircraft awaiting an IFR release. We were cleared for take off at approximately 6:40am. We started with left traffic touch and go's on 4L. After three touch and go's Chandler tower transferred us to right traffic on 4R and to change to frequency 133.1. Tower notified us that there were helicopters, which is typical for Chandler, and I remember there to be one or two at the departure end. We did six touch and go's on 4R. Each time in the pattern we were getting cleared for touch and go number two behind a Seminole. I was also verifying position of the helicopters in their Charlie pattern. On at least one circuit, possibly the first, helicopters on the departure end were noted by tower that I located and had in sight. On the seventh circuit I checked on the turn to downwind for any traffic visually and on my kneeboard iPad, and saw that only the Seminole (which had an Oxford tail number). Around midfield we were again cleared for touch and go, number two following the Seminole. I told Jason we can simulate a power off landing if we have adequate spacing with the Seminole. I watched the Seminole approach the numbers and after abeam I indicated we would have enough spacing and told Jason we'll power to idle but not to put in any flaps yet. Usually we would put one notch of flaps in abeam the numbers. I expected that Jason would need prompting from me for the base turn, however he started the base turn early - likely a result of engine out exercises we had done in the southwest practice area. This would place us higher and closer to the airport than expected, but more than guarantee we would make the runway. I told Jason we can square out our pattern since we had plenty of altitude, and also continued to verify we were clear on traffic on our path to the runway. Just prior to the turn to final I pointed out that we had the runway made and so Jason can fully extend the flaps, which he complied. Being above normal glidepath I suggested I demonstrate a forward slip on final while he shadowed the controls. In the forward slip we had a clear view of the runway ahead of us and could see that we were aligned on a stabilized approach. At approximately 300 feet AGL (~1500 MSL) we heard and felt a bang and I saw what appeared to be black birds to the right. I said "my controls" and Jason stopped shadowing the controls. Aircraft was vibrating and I thought birds had hit the propeller and landing gear due to the perceived location of the impact under the aircraft and a slight drag pull to the right. I called, "Chandler Tower, 2868H has an emergency we hit some birds and possible landing gear; please check my landing gear" while proceeding over the runway. Chandler replied, "2868H your gear is down, clear to land", which I understood to mean that all three gear are down and visible. However on touchdown I felt the left wing continue to drop and in spite of compensating with right aileron and rudder, the aircraft banked left due to no left landing gear. I kept the elevator aft but I did not use the brakes to prevent spinning and reduce load on the gear. We slowed on the runway, slid off to the left, and came to a stop just left of 4R in the dirt at around 7:45am. We cleared the aircraft as quickly as possible and returned a few minutes later to clear out the aircraft once no fire was confirmed. I saw that the left gear was missing, and was surprised that the nose wheel was also missing. The right gear was intact however with damage to the fiberglass around the strut. This surprised me and did not appear to be the result of a bird strike. On the ground Jason pointed out a plume of smoke forming from the approach end of the runway. I used my handheld radio to contact Chandler and ask if they saw what we impacted. They replied they did not know and advised us to remain with the aircraft. Chandler PD arrived within minutes to secure the location.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

Charlie pattern ATC procedures should be published so that pilots are aware of the possibility of simultaneous approaches to 04R or 22L and taxiway Charlie, and any traffic boundaries as the approach paths may overlap during descent.

ATC should not clear simultaneous approaches unless both aircraft have reported the other in site or are specifically sequenced with respect to each other "cleared for the option #3 behind the aircraft".

During simultaneous Charlie pattern operation ATC should extend the aircraft at pattern altitude and call their base if clearing an aircraft on the lower altitude Charlie pattern.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☐ Yes ☒ No
(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Total Time/Cycles
On Part

Hours

Cycles

Time Since This Part
Inspected/Overhauled

Hours

FUEL & SERVICES INFORMATION

Fuel on Board at Last Takeoff
(Convert from pounds, as necessary)

34 Gallons

Fuel Type

☐ 80/87 ☐ 115/145 ☐ Jet B ☐ Other, specify _____
☒ 100 Low Lead ☐ Jet A ☐ JP8
☐ 100/130 ☐ Jet A-1 ☐ Automotive

Other Services, if Any, Prior to Departure

EVACUATION OF AIRCRAFT

Was an emergency evacuation of the aircraft performed? ☒ Yes ☐ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

Instructor unlatched and opened right door as aircraft came to a stop, both instructor and student unbuckled seatbelts and exited right (east) of the aircraft.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

N412TL

Manufacturer: Robinson

Model: R22

Damage to Other Aircraft

☒ Destroyed ☐ Minor
☐ Substantial ☐ None

Registered Owner of Other Aircraft

Name: DELTA LEASING INC DBA

City: Chandler

State: AZ ZIP: 85286

Country: USA

Pilot of Other Aircraft

Name:

City:

State: ZIP:

Country:

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

10/07/2021

mm/dd/yyyy

Name of Pilot/Operator: William Summerfield Dubel

Signature: _____

-- or --



Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or --



Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

WPR22FA001

Reviewed by NTSB Regional Office

AS-WPR

Name of Investigator

Eric M. Gutierrez

Date Report Received

10/8/2021