

WPR22FA021

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane's tailcone and empennage (Courtesy of California Highway Patrol)



Photograph 2 - View of tree from to the north showing impact scar (Courtesy of California Highway Patrol)



**Photograph 3 - View of weather during search and rescue activities, the day after the accident
(Courtesy of California Highway Patrol)**