



Photo 1 – Aerial view of N40KA accident site and terrain (Courtesy of King County Search and Rescue)



Photo 2 – Aerial view of N40KA confined area wreckage site (Courtesy of King County Search and Rescue)



Photo 3 – Ground view of initial point of impact with trees (Courtesy of IIC)



Photo 4 – View of N40KA wreckage facing west and starting from propeller hub to empennage (Courtesy of IIC)