

WPR22FA068

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the main wreckage and accident site.



Photograph 2 - View of the main wreckage and accident site.



Photograph 3 - View of the main wreckage and accident site.



Photograph 4 - Aerial view of the main wreckage and accident site. Courtesy of San Diego County Sheriff.



Photograph 5 - View of the wreckage Examination. Courtesy of Honeywell.