




Photo 1 – Google earth image showing the five job sites, the accident location, and the power distribution lines.



Photo 2 -Overhead image showing the accident location and the power distribution lines. Photo courtesy of the Fresno County Sheriff's Department.



Photo 3 -Top view.



Photo 4 – Underside view.



Photo 5 – Main rotor assembly, and transmission.



Photo 6 – Tail rotor assembly and 90-degree gearbox.



Photo 7 -Left view at the recovery facility.



Photo 9 -Engine at the recovery facility.




Photo 10 – Engine output shaft and a section of fire wall that wrapped around the output shaft.



Photo 11 – Items found in the debris field.