



Photo 1 – Accident airplane flight track




Photo 2 – Accident airplane at accident site



Photo 3 – Quartering view of accident airplane at accident site



Photo 4 – Accident airplane prior to wreckage examination



Photo 5 – View of Marin Headlands from Golden Gate Bridge north tower at time of accident



Photo 6 – North looking view from below the Golden Gate Bridge South Tower



Photo 7 – View while airplane heading south with Marin Headlands (accident site) to the right and cloud cover (Courtesy of passenger’s family)