

WPR22FA216

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the main wreckage and accident site.



Photograph 2 - View of the main wreckage and accident site.



Photograph 3 - View of the main wreckage and accident site.



Photograph 4 - View of the main wreckage and accident site.



Photograph 5 - Rear Propeller



Photograph 6 - Front Propeller



Photograph 7 - Elevator Control Linkages