

WPR22FA256

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the main wreckage and accident site.



Photograph 2 - View of the main wreckage and accident site.



Photograph 3 - View of the main wreckage and accident site.



Photograph 4 - Recovered front engine.



Photograph 5 - Recovered rear engine.