


WPR22FA264

NTSB-ACCIDENT SITE PHOTOGRAPHS



Photograph 1 - Accident site, tree strikes.



Photograph 2 - Accident site, ground scars and main wreckage.



Photograph 3 - Accident site, main wreckage.



Photograph 4 - Accident site, main wreckage.



Photograph 5 - Accident site, upper cowling.



Right Side Cowling
Aft Latch Assembly

Photograph 6 - Accident site, upper cowling right aft latch.



Photograph 7 - Accident site, upper cowling left aft latch.