

WPR22FA298

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the main wreckage and accident site.



Photograph 2 - View of the wreckage debris path.



Photograph 3 - View of the engine and propeller.



Photograph 4 - Recovered propeller and engine.



Photograph 5 - View of the aft side of the recovered engine.