



Photo 1 – Front view of accident airplane (photo courtesy of the FAA)



Photo 2 - View of aft fuselage damage (photo courtesy of the FAA)



Photo 3 - View of right wing damage (photo courtesy of the FAA)



Photo 4 - View of accident airplane tailwheel (photo courtesy of the FAA)