



Photo 1 – View of the accident site. (Courtesy of the FAA)



Photo 2 – View of the airplane’s structural damage, lower cabin area. (Courtesy of the FAA)



Photo 3 – View of the airplane's structural damage, cabin area. (Courtesy of the FAA)



Photo 4 – Debris found in the fuel selector valve. (Courtesy of the FAA)