

## PHOTOGRAPHS



*Figure 1: Wreckage*



*Figure 2: Left and Right Control Columns*




*Figure 3: Left Control Colum*



*Figure 4: Aileron Chain and Elevator Cable Connections at the Control Column*




*Figure 5: Overview of Cable Attach Points*



*Figure 6: Forward Cable in Attach Point (Unknown Material Inside)*



*Figure 7: Closeup of Attach Point*



*Figure 8: Right Control Column*



**FRONT FRAME**



**NO. 5 UPPER**



**NO. 5 LOWER**

*Figure 9: Pulleys*



*Figure 10: No. 9 Pulley with Hook Attachment*



*Figure 11: Up-close of No. 9 Pulley*



*Figure 12: Items Found in Airplane*



*Figure 13: Control Tubes to Elevator*



*Figure 14: Part of Elevator and Bellcrank*



*Figure 15: Left Horizontal Stabilizer and Left Elevator*