



Photo 1 – Accident site, main wreckage. (Courtesy of airplane owner)



Photo 2 – Accident site, airplane's ballistic recovery system. (Courtesy of airplane owner)



Photo 3 – Accident site, cabin instrument panel. (Courtesy of airplane owner)



Photo 4 – Accident site, left wing damage. (Courtesy of airplane owner)



Photo 5 – Accident site, aft fuselage. (Courtesy of airplane owner)



Photo 6 – Accident site, main wreckage. (Courtesy of airplane owner)