



Photo 1 – Accident site, debris field and culvert. (Courtesy of the FAA)



Photo 2 – Accident site, debris field and view of the aft side of the airplane. (Courtesy of the FAA)



Photo 3 – Accident site, view of the forward left side of the airplane. (Courtesy of the FAA)



Photo 4 – Accident site, view of the aft right side of the airplane. (Courtesy of the FAA)



Photo 5 – Accident site, view of the forward side of the airplane. (Courtesy of the FAA)



Photo 6 – Accident site, view of the leading edge of the right wing. (Courtesy of the FAA)