



Photo 1 – View of the accident airplane at the accident site, courtesy of local law enforcement.



Photo 2 - View of the accident airplane at the accident site, courtesy of local law enforcement.



Photo 3 – View of the outlet fuel line at the fuel servo.



Photo 4 - View of the outlet fuel line at the fuel servo (with fuel leaking from the fitting)



Photo 5 – Recovered airplane



Photo 6 - Recovered airplane engine