



Photo 1 – Left side view of airplane (photo courtesy of the NTSB)



Photo 2 - Rear view of airplane (photo courtesy of the NTSB)



Photo 3 – Right side view of airplane (photo courtesy of the NTSB)



Photo 4 - View of airplane undercarriage damage (photo courtesy of the NTSB)



Photo 5 - View of airplane undercarriage damage (photo courtesy of the NTSB)



Photo 6 - View of left main landing gear pivot assembly (photo courtesy of the NTSB)



Photo 7 - View of left main landing gear pivot assembly (photo courtesy of the NTSB)