



Photo 1 – N9YY, at the accident site. Photo Courtesy of the Riverside County Sheriff’s Department.



Photo 2 – Rear View. Photo Courtesy of the Riverside County Sheriff's Department.



Photo 3 – Right view. Photo courtesy of the Riverside County Sheriff's Department.



Photo 4 – Left view. Photo courtesy of the Riverside County Sheriff's Department.



Photo 5 - Fuel shut off valve with the valve handle as found.