



Photo 1 – Aft view of accident airplane from left wing (Courtesy of Federal Aviation Administration)



Photo 2 – View of right wing (courtesy of Federal Aviation Administration)



Photo 3 – View of right wing aft strut and attachment clevis (courtesy of accident pilot)