



Photo 1 – Accident airplane, propeller strike. (Courtesy of the operator)



Photo 2 – Accident airplane, view of the lower forward fuselage. (Courtesy of the operator)



Photo 3 – Accident airplane, view of the lower forward fuselage. (Courtesy of the operator)



Photo 4 – Accident airplane, view of the lower forward fuselage. (Courtesy of the operator)



Photo 5 – Cabin floor area. (Courtesy of the operator)



Photo 6 – Cabin floor area. (Courtesy of the operator)




Photo 8 - Firewall and nose landing gear attachment. (Courtesy of the operator)