



Photo 1 – Belly Damage (Strive Aviation Photo)



Photo 2 – Right Main Landing Gear



Photo 3 – Left Main Landing Gear



Photo 4 - Nose Gear (Extended)



Photo 5 – Nose Gear Doors (Retracted)



Photo 6 – Nose Gear (Partial Extension)