



Photo 1 – Accident site, main wreckage. (Courtesy of the FAA)




Photo 2 – Accident site, runway contact marks. (Courtesy of the FAA)



Photo 3 – Accident site, left main gear strut. (Courtesy of the FAA)



Photo 4 – Accident site, left main gear strut. (Courtesy of the FAA)



Photo 5 – Accident site, wheel pant and strut separation surface. (Courtesy of the FAA)



Photo 6 - Accident site, wheel pant and strut separation surface. (Courtesy of the FAA)



Photo 7 - Accident site, wheel pant and strut separation surface. (Courtesy of the FAA)



Photo 8 - Accident site, wheel pant and strut separation surface. (Courtesy of the FAA)