



Photo 1 – View of accident airplane on open field (courtesy of FAA)



Photo 2 – View of left wing fuel tank opening (photo courtesy of FAA)



Photo 3 - View of right wing right main fuel tank opening (photo courtesy of FAA)



Photo 4 – View of fuel selector valve lever position in the OFF position (courtesy of the FAA)



Photo 5 – View of left wing left auxiliary fuel tank opening



Photo 6 - View of right wing right auxiliary fuel tank opening



Photo 7 – View of removed top spark plugs



Photo 8 – View of opened up carburetor



Photo 9 – View of removed right magneto



Photo 10 – View of removed left magneto