



Photo 1 – View of left-wing damage (photo courtesy of the pilot)



Photo 2 - View of elevator damage (photo courtesy of the pilot)



Photo 3 - View of left brake line damage (photo courtesy of the pilot)



Photo 4 - View of left brake line damage (photo courtesy of the pilot)