




Photo 1 – Post-accident view of damage to left wing auxiliary spar (Courtesy of FAA)



Photo 2 – Post-accident view of damage to the left butt rib (Courtesy of FAA)



Photo 3 – Post-accident view of damage to the left aileron (Courtesy of FAA)