

SERVICEABLE
(Component) D-3000

<u>Magneto</u>	<u>Bendix</u>
Component Name	Mfg. Name
<u>10-682560-11</u>	<u>B000484</u>
Model or Type	Serial No.

The aircraft component identified above was,

☐ Repaired ☒ Overhauled

☒ Tested ☒ Inspected

in accordance with Federal Aviation Regulations and was found to be airworthy for return to service after installation, adjustment and log entry by a qualified individual per §65.81 and §43.9 (a). See reverse side for details.

Invoice # 217128 TSOH _____

Signed _____

Date 9-12-17

Fish Creek Airmotive

Palmer, AK. 99645

Photo 1 – View of magneto overhaul airworthiness component tag (Courtesy of Builder)

10-682560-11 B000484

Disassembled, cleaned, inspected and overhauled magneto. Replaced the following parts; Contacts, condensers, bearings, screws and washers, cam screw, distributor brushes, felts, impulse spring, and cotter. The following AD's were checked for compliance;

74-26-09 - Bushing is steel and has step.

78-18-04 - PCW

79-12-07 - Green block not installed.

79-18-06 - PCW K on data tag.

80-17-14 - PCW

82-11-05 - L on gears X on data tag

82-20-01 - Hardness checked OK

96-12-07 - Cam is snap ring style and measured .005" and found airworthy. Next inspection due in 500 hours.

This Magneto was bench tested and is returned to service after proper installation, adjustment and log entry by a qualified person IAW §65.81 and §43.9 (a). End.

Photo 2 -View of dual magneto overhaul airworthiness component tag details (Courtesy of Builder)