



Photo 1 – View of leading-edge damage to right elevator (photo courtesy of operator)