



Photo 1 – Main rotor blade, delamination damage (Courtesy of the SBCSD).



Photo 2 – Main rotor blade “Blue,” lower surface. (Courtesy of the SBCSD)



Photo 3 – Main rotor blade “Yellow,” lower surface. (Courtesy of the SBCSD)



Photo 4 – Main rotor blade “Red,” lower surface. (Courtesy of the SBCSD)




Photo 5 – Main rotor blade “Blue,” upper surface. (Courtesy of the SBCSD)



Photo 6 – Main rotor blade “Red,” upper surface. (Courtesy of the SBCSD)



Photo 7 – Main rotor blade “Yellow,” upper surface. (Courtesy of the SBCSD)



Photo 8 – Main rotor blade surfaces. (Courtesy of the SBCSD)