



Photo 1 – View of left-wing damage (courtesy of the FAA)



Photo 2 – View of damaged to the left-wing spar (courtesy of the FAA)