



Photo 1 – View of the recovered wreckage.



Photo 2 - View of the recovered wreckage.



Photo 3 - View of the recovered engine.




Photo 4 – No. 2 Cylinder Exhaust Valve



Photo 5 – No. 2 Cylinder Intake and Exhaust Valves