



Photo 1 – Left wing strut damage(photo courtesy of pilot)



Photo 2 – Rudder damage(photo courtesy of pilot)