



Photo 1 – View of side load ground scars (Courtesy of FAA)



Photo 2 – View of substantial damage to the left wing (Courtesy of FAA)