



**Photo 1 – Front view of airplane (photo courtesy of airport operations)**



**Photo 2 – View of right horizontal stabilizer and elevator damage (photo courtesy of airport operations)**