



Photo 1 – Front view of accident airplane (photo courtesy of Airport Operations)



Photo 2 – Rear view of accident airplane (photo courtesy of Airport Operations)



Photo 3 – View of left Horizontal Stabilizer damage (photo courtesy of Airport Operations)