



Photo 1 – View of Left Wing Damage (Courtesy of Pilot)



Photo 2 – View of Left Horizontal Stabilizer Damage (Courtesy of Pilot)