


YEAR 20 <u>22</u> DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries)
9/8/22	0		0	NEW BUILD. - ALL PARTS CLEANED. DE BURED - PRIMED EPOXY PRIMER PAINTED WITH PPG - SINGLE STAGE. EVERYTHING BUILT ACCORDING TO LOCKWOOD CONSTRUCTION MANUAL. ELT DUE AUG - 2027 I certify that this Aircraft has been inspected in accordance with the scope and detail of Appendix D to Part 43 and has been found to be in condition for safe operation  L. END


YEAR 20 _____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT
9/22/2022		IS
CERT. F. UAT		
S.P. GASKÉ		

te Number of
specific entries.)

We

2

[illegible]



The Standard

ENGINE LOG

RIGHT

ASA-SE-2

The Standard
 ENGINE LOG
LEFT

ASA-SE-2

2/21/21, 3pm Pilot's house, P

