




Photo 1 – Diagram of powerlines in relation field and accident site




Photo 2 – Diagram of accident site in relation to powerlines (courtesy of Glenn County Sheriff's Office)



Photo 3 – Quartering view of accident airplane at accident site




Photo 4 – Overview of final moments from Satloc data



Photo 5 – View of airplane from front at accident site