

WPR23FA173

INVESTIGATION PHOTOGRAPHS



Photograph 2 - View of aircraft from north to south (Courtesy of IIC)



Photograph 3 - View of airplane from east to west (Courtesy of IIC)



Photograph 4 - View of airplane from south to north (Courtesy of IIC)



Photograph 5 - View of debris field (Courtesy of FAA)