

WPR23FA185

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Wreckage Under Water (Courtesy of LASD)



Photograph 2 - Wreckage Layout (Courtesy of NTSB)



Photograph 3 - Wreckage _ Left Side (Courtesy of NTSB)



Photograph 4 - Left Wing (Courtesy of NTSB)



Photograph 5 - Right Wing (Courtesy of NTSB)



Photograph 6 - Left Engine (Courtesy of NTSB)



Photograph 7 - Right Engine (Courtesy of NTSB)



Photograph 8 - Fuselage Fittings and B-Nuts (Courtesy of NTSB)

