

WPR23FA223

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of Pinal County SAR)



Photograph 2 - Screenshot from Video of Impact (Courtesy of Witness Baldwin)



Photograph 3 - Airplane Wreckage (Courtesy of NTSB)



Photograph 4 - Recovered Engine Components (Courtesy of NTSB)



Photograph 5 - Propeller Blade (Courtesy of NTSB)