

WPR23LA108

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of crash site (Courtesy of landowner)



Photograph 2 - Wreckage and deployed parachute



Photograph 3 - Engine exam