

WPR23FA287

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aerial View of Accident Site (Courtesy of Law Enforcement)



Photograph 2 - Overview of Main Wreckage



Photograph 3 - View of Main Wreckage from the Right Side



Photograph 4 - View of Main Wreckage - Empennage and Tail



Photograph 5 - View of Right Horizontal Stabilizer



Photograph 6 - View of Left Horizontal Stabilizer



Photograph 7 - View of Engine



Photograph 8 - Cockpit Area