



Photo 1 – First point of impact (courtesy of West Jordan Police Department)



Photo 2 – Aerial view of main wreckage (courtesy of West Jordan Police Department)



Photo 3 – Aerial view of main wreckage (courtesy of West Jordan Police Department)



Photo 4 – Separated section of propeller blade at first point of impact with main wreckage in background (courtesy of West Jordan Police Department)



Photo 5 – Closeup view of main wreckage at accident site (Courtesy of West Jordan Police Department)