



Photo 1 – Quartering view of accident airplane at site



Photo 2 – Separated left wing



Photo 3 – Spliced wing spar and sleeve



Photo 4 – Spliced wing spar and sleeve



Photo 5 – Spliced wing strut attachment and sleeve



Photo 6 – Propeller and propeller hub